

# KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT:

STATEMENT

DATE OCCURRED 4-26-98

DATE REPORTED \_\_\_\_\_

TIME OCCURRED 1600

TIME REPORTED \_\_\_\_\_

LOCATION(S) OF OCCURRENCE:


NORDSTROM LEASEHOLD, WEST SIDE

REPORTED BY:

PHONE NO(S): \_\_\_\_\_

SUMMARY:

THE ANTONOV PARKED AT SPACE 21 THIS WEEKEND ON-LOADED AN ERICKSON AIR-CRANE HELICOPTER AND ASSOCIATED SUPPORT EQUIPMENT FOR DELIVERY TO BRUNEI. THE LOADING HAD TO BE DONE VIA THE FRONT OF THE AN-124, AND DURING THE STAGING OF THE EQUIPMENT ABOUT 1/2 GALLON OF HYDRAULIC FLUID LEAKED ONTO THE NORDSTROM RAMP NORTH OF THEIR FUEL DISPENSER STATION. I OFFERED OUR SPILLMATE TO THE ERICKSON PEOPLE AND THE SPILL WAS TAKEN CARE OF AT 1610. THE CONCRETE IS STAINED IN ABOUT A 2' DIAMETER.



STEVE REAVIS  
Assistant Field  
Maintenance Manager

OFFICERS: [Signature]

ACTION: \_\_\_\_\_

3100 Willow Springs Rd.  
P.O. Box 3247  
Central Point, OR 97502

Hm.: (541) 664-4557  
Phone: (541) 664-5544  
FAX: (541) 664-2312

c.c. S. Dickie